



XDL-6DV1-48V5A-E



**** Note alternate simple on-off operation:**

- Connecting the Purple and Grey output together will provide 0% brightness.
- Leave Purple and Grey output open will provide 100% brightness.


0/1-10V



**** Note alternate simple on-off operation:**


- Connecting the Purple and Grey output together will provide 0% brightness.
- Leave Purple and Grey output open will provide 100% brightness.

VR




** Note alternate simple on-off operation:
 - Connecting the Purple and Grey output together will provide 0% brightness.
 - Leave Purple and Grey output open will provide 100% brightness.

Switch Dim



PWM

**DALI****Ensure DIP switch is set to DALI mode**