

XDL-7DV1-48V5A-E




- ** Note alternate simple on-off operation:
- Connecting the Purple and Grey output together will provide 0% brightness.
 Leave Purple and Grey output open will provide 100% brightness.

0/1-10V




- ** Note alternate simple on-off operation:
- Connecting the Purple and Grey output together will provide 0% brightness.
- Leave Purple and Grey output open will provide 100% brightness.




- ** Note alternate simple on-off operation:
 Connecting the Purple and Grey output together will provide 0% brightness.
 Leave Purple and Grey output open will provide 100% brightness.


Switch Dim



PWM



DALI Ensure DIP switch is set to DALI mode



Ensure DIP switch is set to DMX mode

DMX